

Oil Field Environmental Incident Summary

Incident: 20141026193945 **Date/Time of Notice:** 10/26/2014 19:39
Responsible Party: ENERPLUS RESOURCES USA CORPORATION
Well Operator: ENERPLUS RESOURCES USA CORPORATION
Well Name: GRACE 150-94-06B-07H
Field Name: SPOTTED HORN **Well File #:** 23542
Date Incident: 10/25/2014 **Time Incident:** 19:00 **Facility ID Number:**
County: MCKENZIE **Twp:** 150 **Rng:** 94 **Sec:** 6 **Qtr:**
Location Description: Prairie adjacent to wellsite.

Submitted By: Tony Lucero **Received By:**
Contact Person: Tony Lucero
US BANK TOWER
950 17TH ST STE 2200
DENVER, CO 80202

General Land Use: Pasture **Affected Medium:** Topsoil

Distance Nearest Occupied Building: 2 Mile
Distance Nearest Water Well: 2 Mile

Type of Incident: Fire

Release Contained in Dike: No **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
--	---------	-------	-----------	-------	----------	-------

Oil

Brine

Other

Description of Other Released Contaminant:

Carbon built up on flare tip, when it dislodged, it caused a grass fire affecting an estimated 2 acres. The fire was extinguished.

Inspected: **Written Report Received:** **Clean Up Concluded:**

Risk Evaluation:

Fire hazard. The fire was extinguished.

Areal Extent:

Two acres.

Potential Environmental Impacts:

An estimated two acres of grass were burned.

Action Taken or Planned:

Meeting with flare manufacturer to develop a response strategy to prevent a recurrence.

Wastes Disposal Location: Not applicable.

Agencies Involved: Three Affiliated Tribes, BIA, and NDIC

Updates

Date: 10/27/2014 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Fire on location. No fluids release according to the report. NDIC retains oversight.